

NPDES #1300 Oily Discharge General Permit Discharge Monitoring Report

Legal Name: KINDER MORGAN LIQUID TERMINALS LLC

Common Name: LINNTON TERMINAL

Facility Location: 11400 NW ST HELENS RD , PORTLAND

Submit report monthly by 15th of following month to:

Oregon DEQ

2020 SW 4th Avenue, Suite 400

Portland, Oregon 97201

Site/File ID #: 32300

County: MULINOMAH

Month/Yearteb 2006

	N	Ionitoring for Oil	/Water Separator / A	NK 3034
Day	Oil and Grease (mg/L)	Visible Sheen	Ethanol and/or MBTE	Flow
	Frequency varies, see permit	Daily, visual observation	Quarterly grab sample, if present on site and in bulk	Daily estimate, when discharging
Limit	10 mg/L monthly, 15 mg/L daily max.	No visible sheen at any time	No limit	No limit
]				
2				
3				
4				
5				
<u>6</u> 7	<u> </u>			
8				
9				
10	· · · · · · · · · · · · · · · · · · ·			
11				
12	Y			
13				
14		Y	11/.	
15	1	<u> </u>	110	
16		1.0	//	
17				
18			1	
19 20				
20				
22				
23				
24	1			
25				
26				
27			_	
28				
29				
30			·	
31				
Γotal				
Max.				
Average				

See Reverse Side for Additional Monitoring and Signature Block



Stormwater Monitoring

Only for facilities required to have NPDES permits for stormwater, per 40 CFR 122.26 Monitoring required for each point identified in the Stormwater Pollution Control Plan

Day	Visible Sheen	Floating Solids (associated with industry)	Total Copper (mg/L)	Total Lead (mg/L)	Total Zinc (mg/L)	pH (S.U.)	Total Suspended Solids (mg/L)
	Daily when discharging, visual observation	Once per month when discharging	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample
Limit	No visible sheen	No visible discharge*	0.1 mg/L*	0.4 mg/L*	0.6 mg/L*	Within 6.0 to 9.0	130 mg/L*
1							
2							
3							
4						•	
5	· · · · · · · · · · · · · · · · · · ·						
6							
7							
8	· · · · · · · · · · · · · · · · · · ·						
9							
10						ļ	
11 12							
13			•				
14							
15							
16							
17						<u> </u>	
18		· · · · · · · · · · · · · · · · · · ·					
19							
20							<u> </u>
21							
22							
23							
24		,				1	
25							
26							
27							
28							
29							
30							
31							
Total							
Max.							
Average		<u>-</u>					

^{*}These are benchmarks, not effluent limits. If benchmarks are exceeded, review/possible revision of Stormwater plan is required. See permit for more details.

Signature Requirement

I certify, under penalty of law that this documen	it and all attachm	ents were prepar	ed under my direction or	supervision in
accordance with a system designed to assure t	hat qualified pers	sonnel properly ga	ather and evaluate the inf	ormation submitted.
Based on my inquiry of the person or persons v				
information, the information submitted is, to the				
there are significant penalties for submitting fals	se information, in	cluding the possi	bility of fifies and impriso	nment for knowing
violations.	11.	A 1		

Signature of Responsible Official:	nonte	
Name and Title (Please Print):	Tudante	Field Schedules
Date of Signature: $3-3-06$	Telephone:	503 220 /276